

FAX

M/015/050

Date

8/4/97

Number of pages including cover sheet

5

TO: Tony Gallegos
UTAH DOGM

Phone

801 538 5267

Fax Phone

801 359 3940

FROM:

Russell Harms

G-P Gypsum Corporation

P.O. Box 30006

North Las Vegas, NV
89036

Phone

702-643-8100

Fax Phone

702-643-2049

CC:

REMARKS:

☐ Urgent☐ For your review☐ Reply ASAP☐ Please Comment

Original in mail. This^{is} to cover
questions from various telephone
conversations.

-Russ Harms

PS. Last page is copy of authorization
for plant manager to sign.

SIGURD FAX (801) 896-4234



Georgia-Pacific Corporation

P.O. Box 30006
North Las Vegas, Nevada 89036-0006
Telephone (702) 643-8100

M/015/050

August 4, 1997

Mr. Anthony Gallegos
Utah Division of Oil, Gas and Mining
1594 West North Temple Suite 1210
P.O. Box 145801
Salt Lake City, UT 84114-5801

RE: G-P Gypsum Corporation
San Rafael Quarry Plan Amendment
UTU-696850
M/015/50

Dear Mr. Gallegos:

The purpose of this letter is to provide additional information concerning the proposed mining plan revision requested in the June 4, 1997 letter to the Moab District Office of the Bureau of Land Management.

1. Mining of the new areas will not require an equipment storage area since the existing area used for that purpose is nearby. The maximum length of haul road required will be approximately 800 feet (0.4 acre). Approximately 1.5 acres of the existing disturbed area consists of access roads and equipment storage areas.
2. Mining of the area delineated as "Area B" could extend (although unlikely) through an existing dry wash and farther on to a small road. The wash is small and shallow and mining through it is not expected to result in any significant effect on the surface drainage in the area. Similarly, the small road, if approached will be re-routed so that passing access is maintained without the need to disturb land beyond that proposed.
3. Mining of the areas is not expected to result in a significant increase in the current estimated cost of reclamation since the gypsum deposit is relatively uniform in depth and cover and the contour of the surface (level) indicates very little folding of the underlying deposit.
4. Attached to this letter is a copy of the previously submitted aerial photograph that shows the extent of the existing disturbed area. Although it was taken in 1995, the current disturbed area is approximately the same.


Mr. Anthony Gallegos

8/4/97

Page 2

If you have any questions, or require additional information, I can be reached at 702-643-8100.

Sincerely,



Russell Harms

cc: D. Knepfler - BLM Moab

1"-500'

FILE




G-P GYPSUM CORP. EAGLE CANYON QUARRY

SIGNATORY AUTHORIZATION

Pursuant to the requirements of the United States Environmental Protection Agency (USEPA) or the appropriate States, or local regulatory agencies, the Plant Managers of the following Georgia-Pacific plants are hereby authorized to sign all permit applications and compliance reports, and other environmental documents required or requested by the regulatory agencies.

To be signed by a "responsible official" or "duly authorized representative". As responsible official or duly authorized representative, the Plant Manager is expected to consult with the assigned corporate field environmental engineer in exercising this authorization.



David R. Fleiner
Vice President - G-P Gypsum Corp.

27 September 1996
Date